



Montageanleitung Schreibtischserie : F... , O...






Assembly instruction desk range : F..., O...

OS..




FS..



4 x (A)  500165 M8 x 25	8 x (B)  500254 6,3 x 19mm	8 x (C)  500180 M6 x 16mm	4 x (D)  500571	2 x  500279 SW 5 500278 SW 4
--	---	--	--	--


1



je 2 x (A)
(per part)

(bei FS..)

2




"Außen"
"outside"

je 4 x (C)
(per part)

130 540 (mm) 130


je 4 x (B)
(per part)

4



je 2 x (D)

5



1cm

O-Fuss
Höhe: 650 - 850 mm

F-Fuss
Höhe: 650 - 850 mm